Service Information

PI 996_2819



Hygienic cleaning of cabin filter environment with 996 Hygienic Cleaner for Pollen Filter Box

Important facts

- Use 996 hygienic cleaner after every change of cabin filter!
- Consider manufacture instructions to remove or install components!
- Cleaning with 996 need no further flush with water!
- Before applying the product, turn off A/C and ignition!
- Attention! Protect electrical components from humidity!
- We recommend 994 hygienic cleaner for A/C when allergic reactions or bad smell is already present!

Cleaning progress

- 1. Remove cabin filter.
- 2. Spray 996 hygienic cleaner on TUNAP microfiber cloth and cabin air box.
- 3. Wipe cabin filter box and air ducts with wetted microfiber cloth.
- 4. Remove spray nozzle from can, attach probe and insert careful towards evaporator in air ducts and spray shortly in each duct. Let evaporate cleaner for at least 10 min.
- 5. Attention! Protect electrical components from humidity! Don't spray cleaner directly on the fan motor!
- 6. Install new cabin filter.



The specifications provided in this Service Information sheet are the results of careful analysis. Any application-related specifications shall be viewed as recommendations based on past experiences. Due to the wide variety of applications and work methods, we are unable to provide binding specifications. Therefore, there exists no contractual legal relationship, nor will secondary obligations arise from any purchase contracts. Only the most recent version of the Service Information sheet retains its validity.

TUNAP GmbH & Co. KG | D-82515 Wolfratshausen / Germany | Tel. +49 (0)8171 / 16 00 - 0 | info@tunap.com | www.tunap.com